Facilities Work Session



Franklin County Board of Education March 21, 2022

5:30 pm

Dr. Larry Webb, Chief of Auxiliary Services

Update of Current Projects

Location	Project	Status
BHS	Replace/repair parking lot.	complete
CCMS	Replace/repair parking lot.	complete
CCMS	Resurface Lobby Floor	complete
FHS	Replace Wrestling Mat	complete
FMS	Remove basement carpet, replace with polished concrete	complete
FMS	Replace Vestibule Lighting	complete
FMS	Replace/repair parking lot	complete
LES	Repaint Parking Lot Lines	complete
LHS	Shop Roof replacement	complete
LMES	Repaint Parking Lot	complete
LHS	Replace/resurface Gym Roof	complete
YES	Carpet Replacement	complete
YES	Replace/repair parking lot.	complete
BES	New HVAC in Holmes Building	complete
CCMS	New Soccer Field	In Progress
TLMS	Replace/Repair Parking Lot	Defer-needs total replacement

Constal Outland Dudwat of ago

RECURRING

Recurring expense

Recurring expense Recurring expense

Recurring expense

Recurring expense

Recurring expense

Recurring expense

Recurring expense

Capital Outlay Budget of 2022–2023				
CAPITAL OUTLAY 22-23				
PROJECTS				
BES	Gym lobby, Holmes hallway, Cafe roof	\$39,390.00		
BES	GE Roof seal on Gym	\$55,198.00		
BES	Holmes building GE roof seal	\$74,860.00		
BHS	GE roof seal Media, computer lab and 200 blg	\$187,991.00		
BHS	Replace carpet with vct in 100 hall	\$24,882.00		
BMS	Remove carpet from lobby, replace with vct	\$13,635.00		
FES	Gym roof seal	\$66,300.00		
FMS	Replace carpet in band room	\$4,752.00		
LaMES	Roof replacement-cafeteria building	\$56,270.00		
LHS	Fire alarm upgrade	\$49,500.00		
LHS	Replace shingles on boiler building	\$28,680.00		
RES	New metal roof on all mobile units	\$31,253.00		
RES	GE roof seal flat roof surfaces	\$61,980.00		
TLMS	Roof replacement (6th grade shingles)	\$43,315.00		
YES	Roof replacement/seal gym lobby	\$30,818.00		
YES	Replace carpet in 5 rooms	\$14,763.00		
YES	GE seal gym roof and art room	\$56,835.00		
YES	Main lobby flat roof around barrel roof-repairs	\$35,857.00		

Parking lot lights, fire extinguishers

Safety Security/Access

New Maintenance Truck (1)

Paint (system wide)

Capital Outlay Total

Lic/Title Fees

Energy Projects

Security Camera Licensing and Installation

Capital Improvements to Existing Sites

\$40,000.00

\$80,000.00

\$100,000.00

\$100,000.00 \$55,000.00

\$6,000.00

\$42,721.00

\$200,000.00

\$1,500,000.00

BES Roofing

- Gym lobby Cafeteria Flat
- Holmes hall and building Gym and Holmes
- seal














BHS Roof Media 200 Hall Computer Lab









BHS Carpet-old 100 hall





BMS Lobby Carpet to VCT (tile)



FES Gym Flat Roofs










FMS Band Carpet Replace






LaMES Cafeteria Roof







LHS FACP





LHS Shingle Replacement Boiler Building








RES Mobile Units







RES Flat Roof Surfaces







TLMS Sixth Grade Building










YES Roof Gym Lobby






YES New Carpet



YES Roof Gym and Art Room







YES Main Lobby Roof







Additional Needs

In addition to our projects and normal budget items, we have identified two significant items that are quite expensive.

Franklinton Middle School- This is an urgent need. We have repaired the roof, walls, and windows in the courtyard/auditorium area multiple times. The leaks continue inside and outside of the walls. After 99 years, we need to fully renovate the area to avoid further damage, moisture issues, air quality issues and further complications. Interior repairs and renovations can not proceed until these repairs are affected. The roof will need repairs as well. Additionally, the project will require scaffolding and asbestos abatement.

Estimated cost of scaffolding, abatement, and repairs \$505,855-\$605,855.

FMS Windows, Walls, Roof/Auditorium









Additional Needs

Terrell Lane Middle School- Our plans for resurfacing the parking lot this year were changed. Through the design/build process it was determined recently that the lot could not be resurfaced due to the age (not recommended.) We checked with engineers, architects and geotech professionals. A total demolition and new lot is needed. Capital Outlay Fund Balance funds were allocated for the resurface project but are insufficient for the complete renovation.

Total cost is estimated as \$750,000-\$1,000,000.

We have been in communication with the County Manager on these specific larger-scale needs, and she has indicated that they will work with us to develop a plan to address.

TLMS Parking Lot









Capital Outlay 2022-2023-Total Picture

CAPITAL OUTLAY 22-23

BES Gym lobby, Holmes hallway, Cafe roof S39,390.00	
BES GE Roof seal on Gym S55,198.00 S55,198.00 BES Holmes building GE roof seal S74,860.00 S187,991.00 Technology (inventory) S50,000.00 S187,900.00 Technology (inventory) S50,000.00 Technology (inventory) Technology (inventory) Technology (inve	
BES	
BHS	
BHS Replace carpet with vct in 100 hall \$24,882.00 Furniture and Technology (district wide) \$75,000.00	
BMS Remove carpet from lobby, replace with vct \$13,635.00 FES Gym roof seal \$66,300.00 FMS Replace carpet in band room \$44,752.00 LaMES Roof replacement-cafeteria building \$55,000.00 LHS Fire alarm upgrade \$49,500.00 LHS Replace shingles on boiler building \$28,680.00 RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$661,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Replace carpet in 5 rooms \$14,763.00 YES Replace carpet in 5 rooms \$56,835.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Safety Security (Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
FES Gym roof seal \$66,300.00 FMS Replace carpet in band room \$4,752.00 LaMES Roof replacement-cafeteria building \$56,270.00 LHS Fire alarm upgrade \$49,500.00 LHS Replace shingles on boiler building \$28,680.00 RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Sactify Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
FMS Replace carpet in band room \$4,752.00 LaMES Roof replacement-cafeteria building \$56,270.00 LHS Fire alarm upgrade \$49,500.00 LHS Replace shingles on boiler building \$28,680.00 RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
LaMES Roof replacement-cafeteria building \$55,270.00 LHS Fire alarm upgrade \$49,500.00 LHS Replace shingles on boiler building \$28,680.00 RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
LHS Fire alarm upgrade \$49,500.00 LHS Replace shingles on boiler building \$28,680.00 RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$556,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Safety Security/Access \$100,000.00 Recurring expense Safety Security/Access \$100,000.00	
LHS Replace shingles on boiler building \$28,680.00 RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$556,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Safety Security/Access \$100,000.00	
RES New metal roof on all mobile units \$31,253.00 RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
RES GE roof seal flat roof surfaces \$61,980.00 TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
TLMS Roof replacement (6th grade shingles) \$43,315.00 YES Roof replacement/seal gym lobby \$30,818.00 YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
YES Replace carpet in 5 rooms \$14,763.00 YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING \$40,000.00 Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
YES GE seal gym roof and art room \$56,835.00 YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
YES Main lobby flat roof around barrel roof-repairs \$35,857.00 RECURRING \$40,000.00 Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
Recurring expense Parking lot lights, fire extinguishers \$40,000.00 Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
Recurring expense Security Camera Licensing and Installation \$80,000.00 Recurring expense Safety Security/Access \$100,000.00	
Recurring expense Safety Security/Access \$100,000.00	
Recurring expense Capital Improvements to Existing Sites \$100,000.00	
Recurring expense Paint (system wide) \$55,000.00	
Recurring expense Lic/Title Fees \$6,000.00	
Recurring expense New Maintenance Truck (1) \$42,721.00	
Recurring expense Energy Projects \$200,000.00	
Capital Outlay Total \$1,500,000.00	
FUND BALANCE	
Terrell Lane Soccer Field	\$300,000.0
FUND BALANCE TOTAL	\$300,000.0
ESSER HVAC FUNDS	
ESSER HVAC Repairs	\$100,000.0
ESSER 3 year HVAC project YEAR 2	\$2,900,000.0
ESSER TOTAL ESSER TOTAL	\$3,000,000.0
County Funds	
FMS Window, roof and wall r/r \$605,855.00	
TLMS Replace entire parking lot \$1,000,000.00	
County Fund Total \$1,605,855.00	

Fund Balance Impact and Projection

FYE 6/30/2021 Ending FB: \$1,743,610 FYE 6/30/2022 Assigned FB: (\$436,153) 22/23 Allocation (Pending) (\$300,000) FYE 6/30/2023 Projected Ending FB: \$1,007,457

2022 Assigned Fund Balance: CCMS Soccer Field \$431,153 Long Range Facilities \$180,000 TLMS Parking Lot (return \$175,000)

2023 Assigned Fund Balance-Pending Approval: TLMS Soccer Field \$300,000

Questions and Discussion